

Please be prepared to follow the rules/dress code listed below:

Things you need to know

- May will be warm and the mill is a hot place even when it is cool outside. So the earlier in the day the more comfortable your folks will be.
- The facility is located on Germann Road, East of Ellsworth (11444 E. Germann Rd, Mesa, AZ 85212).
 - o It is in the Southeast corner of the city of Mesa... about 40 minutes from Sky Harbor Airport.
- Everyone is required to wear Personal Protective Equipment (PPE). Here is a list of what is required.
 - o Safety glasses – will be provided by CMC, but, if you have your own, please bring them
 - o Hearing protection – will be provided by CMC, but if you have your own, please bring them
 - o Hard hat – will be provided by CMC
 - o Fire-resistant jacket – will be provided by CMC
 - o Closed-toe shoes – you MUST wear closed-toe shoes, or you will not be allowed to tour
 - o Pants – you MUST wear pants, jeans are preferred
 - You will not be allowed to tour if you are wearing shorts, skirts, etc.
 - o Please do not touch anything unless invited by our tour guides. Some of the things you will see can easily cut or burn the skin
 - o Parts of the tour will take place on an elevated walkway, approximately 40 ft. off the ground.
 - If you are unable to climb stairs, or are afraid of heights, please let a CMC representative know prior to starting the tour.
 - o Anyone with a Pacemaker SHOULD NOT be within 10 feet of the fencing around the Induction Furnace in the Mill area. The induction Furnace is an electro-magnetic heating device and can interfere with the proper operation of a pacemaker.
 - o This is a working facility with trucks, cranes, and fork lifts moving about. Please be aware of your surroundings and stay with the rest of the group
 - o Finally, this is a working steel mill, and it is very hot inside the facility. The PPE will make things even hotter, so make sure you are fully



GENERAL MILL RULES FOR CMC STEEL AZ VISITORS

CMC STEEL AZ welcomes you as a visitor to our mill. As always, safety must be our number one priority. In order to provide a safe tour, we ask that you read the following general rules and guidelines. It is required that at all times you stay with your tour guide. There will be many exciting operations and procedures going on around you as you tour through the mill. Always stay alert, watch your footing, and wear your safety equipment at all times.

MEDICAL/PHYSICAL ISSUES:

1. Anyone with a Pacemaker **SHOULD NOT** be within 10 feet of the fencing around the Induction Furnace in the Mill area. The Induction Furnace is an electro-magnetic heating device and can interfere with the proper operation of a pacemaker.
2. Tour Routes through the Melt/Cast area entail climbing and descending of stairs and an elevated walkway. Persons with physical or medical restrictions are advised to begin their tour or join their group at the Training Trailer.
3. High Heat areas are present throughout the various mills and tour route.

GENERAL SAFETY RULES/GUIDELINES:

1. Safety Equipment (hard hat, safety glasses w/ side-shields, flame retardant jackets and sturdy shoes/boots must be worn in the mill at all times. Sandals, open toed shoes, high heels etc. are not acceptable footwear.
2. Hearing Protection must be worn.
3. Stay with your tour guide at all times. Use handrails when on stairs/walkways.
4. Please stay within the designated walkways and away from restricted areas.
5. Do not touch any equipment or product. There are many moving parts, sharp edges, and hot materials.
6. Visitors must always enter and exit the mill through man-doors – NEVER through over-head or equipment doors.
7. Always adhere to mill signage. (No Smoking, Do Not Enter, Crane Overhead, etc).
8. Always look and be aware of overhead crane movement. LOOK UP when entering buildings or passing from bay to bay.
9. Always be aware of your surroundings and all activities going on around you.
10. Always be aware of the nearest exit or escape route: Tour Guide will review with group.
11. Never cross through or go around yellow caution tape or red danger tape.
12. No pictures are to be taken during the tour. This includes camera phones.
13. OSHA states that no one under 18 years of age is permitted on site.

WE SINCERELY HOPE YOU ENJOY YOUR TOUR. HAVE A SAFE AND ENJOYABLE VISIT WHILE AT OUR FACILITY.

Date: _____

Name: _____ Company: _____

WE ASK AT THE END OF YOUR TOUR THAT YOU LEAVE YOUR SAFETY EQUIPMENT WITH YOUR TOUR GUIDE OR WITH A DESIGNATED CMC STEEL AZ REPRESENTATIVE.

THANK YOU – CMC STEEL AZ

MANAGEMENT